Views of
Salem Fire Ruins

AVERY LIBRARY
COLUMBIA UNIVERSITY

FOR the information of architects, engineers and builders in general; we take the liberty of mailing you a few prints of photographs which we had taken from the ruins of the late Salem Fire. These views are self explanatory.

Hoping that the same will be of interest to you and bring you more confidence than ever in the quality of the LALLY COLUMN, we are,

Very respectfully,

U. S. COLUMN CO.

View of the ruins of the French Catholic Church and School, Salem, Mass., after the fire.

Church ruin showing a lot of cast iron columns broken in several pieces.

Interior View of the French Catholic Church, Salem, Mass., showing the ruins after the fire. The small white arrows show the condition of the cast iron columns that were used.



View of the French Parochial School Ruins adjoining the Church, showing the condition of the Lally Columns after the fire at Salem, Mass.

This building was equipped with cast iron columns which were completely destroyed as shown. The white arrows show some of the destroyed cast iron columns.

Note the condition of cast iron columns. White arrows indicate location.

View of Lally Column holding the corner of a building after the fire.

A Salem Ruin showing the condition of the Lally Columns after the fire.

One of the many hundred of residences where Lally Columns were used in the Salem Fire.

Note the condition of all material and contrast with the Lally Columns.

Note carefully the white arrows, they mark the cast iron columns used in the engine house.

AVERY LIBRARY
COLUMBIA UNIVERSITY

AVERY LIBRARY
COLUMBIA UNIVERSITY